

# AudioControl MD\_series Crestron Driver

## Release Notes

**SimplWindows Module:** MD\_series

**Current version:** 3.4.1

## Changes

Date 2022-02-10 - Version - 3.4.1 - Release only for Crestron Home

Date 2022-01-11 - Version - 3.4.0

- Modules Tested:
  - M4800 - 1.2.36
  - M6400 - 1.1.39
  - D4600 - 0.1.25
- Simpl Windows - 4.14.20
- Device Database - 200.00.012.00
- Crestron Database - 200.00.002.00
- Simpl+ - 4.05.01
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.15.04.00

## Enhancements

- Compilers for Series 4 Processors

Date 2021-06-18 - Version - 3.3.0 - Release only for Crestron Home

Date 2020-09-30 - Version - 3.2.1

## Version

- Modules Tested:
  - M4800 - 1.2.36
  - M6400 - 1.1.39
  - D4600 - 0.1.25
- Simpl Windows - 4.14.20
- Device Database - 200.00.012.00
- Crestron Database - 200.00.002.00
- Simpl+ - 4.05.01
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.15.04.00

Date 2020-09-30 - Version - 3.2.1

## Version

- Modules Tested:
  - M4800 - 1.2.36
  - M6400 - 1.1.39
  - D4600 - 0.1.25
- Simpl Windows - 4.14.20
- Device Database - 200.00.012.00
- Crestron Database - 200.00.002.00
- Simpl+ - 4.05.01
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.15.04.00

## Enhancements

- N/A

## **Bug Fixes**

- Fixed - Unhandled Exception: System.NullReferenceException: NullReferenceExceptionat  
CrestronSharp.CrestronSharpCS.\_restartThrottleVolumeTimer()
- Issue believe to be sending command before module had fully initialized

## **Exceptions**

- NA

## **User Impacted**

- Need to add values for poll timer

Date 2020-09-30 - Version - 3.2.0

## **Version**

- Modules Tested:
  - M4800 - 1.2.36
  - M6400 - 1.1.39
  - D4600 - 0.1.25
- Simpl Windows - 4.14.20
- Device Database - 200.00.012.00
- Crestron Database - 200.00.002.00
- Simpl+ - 4.05.01
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.15.04.00

## **Enhancements**

- Adding Volume Control and Audio control for Digital Outputs

## **Bug Fixes**

- NA

## **Exceptions**

- NA

## **User Impacted**

- Need to add values for poll timer

Date 2020-09-25 - Version - 3.1.0

## **Version**

- Modules Tested:
  - M4800 - 1.2.36
  - M6400 - 1.1.39
  - D4600 - 0.1.25
- Simpl Windows - 4.14.20
- Device Database - 200.00.012.00
- Crestron Database - 200.00.002.00
- Simpl+ - 4.05.01
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.15.04.00

## **Enhancements**

- Converted driver to use SIMPL#.

## **Bug Fixes**

- NA

## **Exceptions**

- Dynamic poll timer
- digital singal for getting current status

## **User Impacted**

- Need to add values for poll timer

Date 2020-08-13 - Version - 3.0.0

## Version

- Modules Tested:
  - M4800 - 1.2.36
  - M6400 - 1.1.39
  - D4600 - 0.1.25
- Simpl Windows - 4.14.20
- Device Database - 200.00.012.00
- Crestron Database - 200.00.002.00
- Simpl+ - 4.05.01
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.15.04.00

## Enhancements

- Converted driver to use SIMPL#.

## Bug Fixes

- NA

## Exceptions

- NA

## User Impacted

- If updating to version 3 from a lower version to ensure you update **ALL** modules , e.g. Zone, Group, Analogue and digital.
- Demo VTP has been updated to use Smart Graphics.
- Driver has been updated to use SIMPL#. Where possible, the driver matches version 2 but some changes have been made to improve the driver and configuration.